



Pre-shipment Inspection (PSI)


BASIC INSPECTION INFORMATION		
Product:	Color Catcher	
Brand:	N/A	
Inspection location:	Minhang, Shanghai, China	
Inspection date:	May 14 th ,2026	
Supplier:	XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXXXXXXXXXX	
Factory:	XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXXXXXXXXXX	
Inspector :	Paddy	
Order quantity:	96960boxes	
Qty ready for inspection (%):	96960boxes (<u>100</u> % finished, and <u>100</u> % packed)(See attached qty breakdown)	
Reference sample available:	No	

INSPECTION RESULT JUDGMENT					
OVERALL RESULT: Pending, see remark 1,2,3					
CRITERIA	RESULTS		REMARKS		
1. Quantity	Pass		N/A		
2. Product and packing check	Pending		1,2,3		
3. On-site tests & special requirements	Pass		N/A		
4. Wworkmanship AQL:	Allowed quality level (AQL)		CRI	MAJ	MIN
		Found	0	0	11
		Max	0	14	21
		Checked	500	500	500

REMARKS
1. No any approval sample or essence samples were provided by factory for inspection reference.
2. The factory does not have any spare cartons available for replacement. Only 10 boxes can be disassembled for inspection, and the remaining products will only be inspected for the appearance of the cartons..



3. The factory only sealed “I” shape, but not “工” shape on the outer carton.



INSPECTION STANDARDS	
Inspection type	Final Random Inspection (FRI)- <u>1st inspection</u>
Sampling standard	ANSI/ASQ Z1.4-2008 (MIL-STD-105E)
Sampling Plan (Single)	G-II (<u>normal inspection</u>)
AQL for Critical/ Major/ Minor	0 /1.5/4.0
Sampling size for Cri/Maj/Min	<u>500 / 500 / 500</u>
No. of cartons selected and inspected	No carton number printed on outer carton

1. Quantity	Result : Passed					
Approximate 80%of the total order quantity must be finished and packed	<u>96960 boxes (100 %) units finished and 96960 boxes (100 %)packed into master carton</u>					
	Item#	Oder required	Actual finished	Gift box packed	Master carton packed	S/S
	Color Catcher	96960	96960	N/A	4040	500
	Total	96960	96960	N/A	4040	500

2.Product and packing check (photo)	Result : Pending, see remark 1,2,3
-------------------------------------	------------------------------------



Finished products in warehouse



Finished products in warehouse


Color Catcher



Carton view and shipping mark



Carton view and shipping mark



Carton view and shipping mark



Carton view and shipping mark



Open carton




Open carton



Packing view







Packing view



Packing view



Packing view




Packing view




Packing view




Packing view



Packing view







Packing view




Product view



	
Product view	Product view
	
Product view	Product view
	
Product view	Product view
Carton size and weight	



Carton size check	Carton size check
Carton size check	Carton size check
Carton size check	Carton size check



Carton weight for kitchen cleaning wipes



Carton weight for kitchen cleaning wipes

Packing size and weight



Packing size and weight check



Packing size and weight check



Packing size and weight check



Packing size and weight check



Packing size and weight check	Packing size and weight check
Product size	
Product size check	Product size check
Product size check	Product size check



	
Product size check	Product size check
	
Product weight check	Product weight check

3. ON-SITE TESTS & SPECIAL REQUIREMENTS	Result : Pending, see test requiriement 7
---	---

Test Requirements	Comments from Inspector (Actual finding/photo)	Result
Universal test requirements		



1.Normal function check. (S-3: 32 pcs)
(According to the instruction manual or specification to check each function of product, no any malfunction found)



Pass





2.Bar code scanning test (S-3: <u>32</u> pcs)		Pass
3. 3M tape adhesive test (S-3: <u>32</u> pcs) (Use 3M tape to do this test)	N/A	N/A
4. Internal structure/Major Components check (1-3 pcs per item)	N/A	N/A



5. Carton dimension and weight check (3ctns (The tolerance should be within +/- 5% of the carton size and weight which printed on master carton)	Actual carton size and weight measurement as below:		Pass
	Item#	Printed on master carton	
	Color Catcher	/	
		Actual measuring	
		40x25.4x17.5cm/ 1.75kgs	



6. Carton drop test (1 ctn per item)
(ISTA-1A, 1 corner, 3 edge and 6 face of master carton, height : 76 cm) , no master carton and product damaged.



Pass

Special test requirements (Depend on different product)

7. Transportation test for outer carton (1-2 ctns per item)
Use the factory's transportation test machine to do this test, and check if the product or package has any problem after test

The factory doesn't have equipment to do carton transportation test

Pending



8. Cleaning wipes PH check (S-3: <u>32</u> pcs) Use equipment to check if the PH is during 4-8						Pass
						
9. Smell test (S-3: <u>32</u> pcs) Compare the customer's sample, and check scent of each item)						Pass
4. DEFECTIVES LIST						
Defect description		CRI	MAJ	MIN	Defective Picture	
Item# Color Catcher						


Color box crease - 彩盒折痕	0	0	3	
				
				



Color box is damaged.-彩盒 损伤	0	0	6	
				
				





Dirty mark 彩盒脏污	0	0	1	
Dirty mark 产品脏污	0	0	1	

Item Wood furniture wipes/Kitchen cleaning wipes/Bathroom wipes/Household universal cleaning wipes				
Sample size	Maximum Allowed	Total Defects	Result	Notes
CRI : 500	0	0	Pass	N/A
MAJ : 500	14	0	Pass	N/A
MIN : 500	21	11	Pass	N/A

Remark: If no found the relevant AQL for the item reference, pls refer the AQL of most proximate sample size. for example, no AQL for sample size 150 pcs, pls refer the AQL of most proximate sample size of 125 pcs. If the AQL failed, the overall inspection result should be rejected, and pls make a remark like "Rejected due to AQL failed for item XXXX" on the first page of report.

End of the Report